



State of Connecticut **ACCIDENT INFORMATION SUMMARY**

CFS #: 1700247212

Department of Emergency Services and
Public Protection / Division of State Police

Date: 05/09/2017

Time: 14:16

State Police Troop: TROOP L

Primary Officer: PORTORREAL, JOEL J

Location: Sherman Hill Rd Woodbury

Intersection: Tuttle Rd

Involved Vehicles

Vehicle #: 1

Owner: Berman, Christopher

Address: [REDACTED]

Plate: [REDACTED]

State: CT

Make: Lexus

Model: SC 430

Year: 2003


Vin: [REDACTED]

Insurance Co.: CHUBB NATIONAL INSURANCE

Policy #: [REDACTED]

Vehicle Towed: Yes Towed To: [REDACTED]

Damaged Area: All Areas Not Applicable Not Applicable



Vehicle Damage Diagram

Vehicle #: 2

Owner: Bertulis, Edward

Address: [REDACTED]

Plate: [REDACTED]

State: CT

Make: Ford

Model: Escape X

Year: 2003


Vin: [REDACTED]

Insurance Co.: HARTFORD INSURANCE COMPA

Policy #: [REDACTED]

Vehicle Towed: Yes Towed To: [REDACTED]

Damaged Area: All Areas Not Applicable Not Applicable



Vehicle Damage Diagram

Involved Persons

Vehicle #: 1

Name: Berman, Katherine Ann

Sex: F

D.O.B.: 10/25/1949

OP State & No.: CT

[REDACTED]

Address: [REDACTED]

Status: Driver

Seating Position: Front Left(usually the motor veh or motorcycle driver except for postal vel

Protection System: Shoulder and Lap Belt Used

Airbag Status: Deployed-Front

Injuries: Fatal Injury

Transported: No Transported By:

Hospital:

Vehicle #: 2

Name: Bertulis, Edward

Sex: M

D.O.B.: 12/28/1929

OP State & No.: CT

[REDACTED]

Address: [REDACTED]

Status: Driver

Seating Position: Front Left(usually the motor veh or motorcycle driver except for postal vel

Protection System: None Used-Motor Vehicle Occupant

Airbag Status: Deployed-Combination

Injuries: Fatal Injury

Transported: Yes Transported By: Woodbury EMS

Hospital: WATERBURY HOSP.

Vehicle 2 was traveling east on Sherman Hill Road approximately 100 feet east of Tuttle Road in the town of Woodbury. Vehicle 1 was traveling east on Sherman Hill Road directly behind Vehicle 2. Vehicle 2 was struck in the rear end by the front end of Vehicle 1. Following the initial contact between both vehicles, Vehicle 1 continued east, veering off the roadway to the right, down a small embankment and overturned into a small body of water. Vehicle 2 veered off the roadway to the right, collided with a utility pole and landed in the center of the roadway on its roof. The contact between both vehicles resulted in the death of both operators. Both, Vehicle 1 and Vehicle 2, sustained heavy disabling damage and were towed from the scene. Operator 2 was initially transported to Waterbury Hospital for sustaining serious life-threatening injuries. The cause of this collision remains under investigation.

	SUPERVISOR SIGNATURE AND BADGE NO. [REDACTED]	DATE SIGNED 05/09/2017
--	--------------------------------------------------	---------------------------